

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
6: Okoboji-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Hard to pack	1.00 0.85	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
34: Estherville-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
34B: Estherville-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
34C2: Estherville-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
55: Nicollet-----	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone Piping	0.02 0.01	Somewhat limited Deep to water Slow refill Cutbanks cave	0.68 0.30 0.10
62C: Storden-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
62D: Storden-----	Somewhat limited Seepage Slope	0.70 0.01	Very limited Piping	1.00	Very limited Deep to water	1.00
62E: Storden-----	Somewhat limited Seepage Slope	0.70 0.04	Very limited Piping	1.00	Very limited Deep to water	1.00
62F: Storden-----	Somewhat limited Seepage Slope	0.70 0.18	Very limited Piping	1.00	Very limited Deep to water	1.00
72: Estherville-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
72B: Estherville-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.98	Very limited Deep to water	1.00
73C: Salida-----	Very limited Seepage	1.00	Somewhat limited Seepage	0.95	Very limited Deep to water	1.00
90: Okoboji-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Hard to pack	1.00 0.72	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
95: Harps-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00 0.01	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
107: Webster-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
133: Colo-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
133B: Colo-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
138B: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
138C: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
138C2: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
138D2: Clarion-----	Somewhat limited Seepage Slope	0.70 0.01	Very limited Piping	1.00	Very limited Deep to water	1.00
141: Watseka-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.36	Very limited Cutbanks cave Deep to water	1.00 0.01
150: Hanska-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.37	Very limited Cutbanks cave	1.00
172: Wabash-----	Not limited		Very limited Depth to saturated zone Hard to pack	1.00 1.00	Very limited Slow refill Cutbanks cave	1.00 0.10
181B: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
181C2: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
203: Cylinder-----	Very limited Seepage	1.00	Somewhat limited Seepage Depth to saturated zone	0.85 0.43	Very limited Cutbanks cave Deep to water	1.00 0.25
221: Palms-----	Very limited Seepage	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Cutbanks cave	0.10
224: Linder-----	Very limited Seepage	1.00	Somewhat limited Seepage Depth to saturated zone	1.00 0.43	Very limited Cutbanks cave Deep to water	1.00 0.25

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
253C: Farrar-----	Very limited Seepage	1.00	Somewhat limited Piping Seepage	0.88 0.09	Very limited Deep to water	1.00
259: Biscay-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.85	Very limited Cutbanks cave	1.00
274: Rolfe-----	Somewhat limited Seepage	0.57	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
308: Wadena-----	Very limited Seepage	1.00	Somewhat limited Seepage	1.00	Very limited Deep to water	1.00
324: Dickman-----	Very limited Seepage	1.00	Somewhat limited Seepage	1.00	Very limited Deep to water	1.00
324B: Dickman-----	Very limited Seepage	1.00	Somewhat limited Seepage	1.00	Very limited Deep to water	1.00
339: Truman-----	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.96	Very limited Deep to water	1.00
339B: Truman-----	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.96	Very limited Deep to water	1.00
354: Marsh-----	Not rated		Not rated		Not rated	
390: Waldorf-----	Somewhat limited Seepage	0.57	Very limited Depth to saturated zone Hard to pack	1.00 0.07	Somewhat limited Slow refill Cutbanks cave	0.43 0.10

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
485: Spillville-----	Very limited Seepage	1.00	Somewhat limited Piping	0.88	Somewhat limited Deep to water Cutbanks cave	0.81 0.10
485B: Spillville-----	Very limited Seepage	1.00	Somewhat limited Piping	0.88	Somewhat limited Deep to water Cutbanks cave	0.81 0.10
506: Wacousta-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
507: Canisteo-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
511: Blue Earth-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00 1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
559: Talcot-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.85	Very limited Cutbanks cave	1.00
585B: Colo-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
638B: Clarion-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00
639C: Storden-----	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Very limited Deep to water	1.00

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
639D: Storden-----	Somewhat limited Seepage Slope	0.70 0.01	Very limited Piping	1.00	Very limited Deep to water	1.00
639E: Storden-----	Somewhat limited Seepage Slope	0.70 0.04	Very limited Piping	1.00	Very limited Deep to water	1.00
655: Crippin-----	Somewhat limited Seepage	0.70	Somewhat limited Piping Depth to saturated zone	0.50 0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10
658: Mayer-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.93	Very limited Cutbanks cave	1.00
733: Calco-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00 0.01	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
823: Flagler Variant----	Very limited Seepage	1.00	Somewhat limited Seepage	1.00	Very limited Deep to water	1.00
823B: Flagler Variant----	Very limited Seepage	1.00	Somewhat limited Seepage	1.00	Very limited Deep to water	1.00
895: Mayer-----	Very limited Seepage	1.00	Very limited Depth to saturated zone Seepage	1.00 0.93	Very limited Cutbanks cave	1.00
C485: Spillville-----	Very limited Seepage	1.00	Somewhat limited Piping	0.88	Somewhat limited Deep to water Cutbanks cave	0.81 0.10

FIELD OFFICE TECHNICAL GUIDE Sec. II
ENGINEERING INTERPRETATIONS

Water Management

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Palo Alto County, Iowa

Map symbol and soil name	Pond reservoir areas		Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
T6: Okoboji-----	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Hard to pack	1.00 0.70	Somewhat limited Slow refill Cutbanks cave	0.30 0.10
W: Water-----	Not rated		Not rated		Not rated	